

PCN Number:	20170915002	PCN Date:	Oct. 6, 2017
Title:	Datasheet for LP8860-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



LP8860-Q1

SNVSA21F –MAY 2014–REVISED JULY 2017

Changes from Revision E (November 2016) to Revision F	Page
• Changed placement of "7" data hold time in Figure 2	13
• Deleted "The LP8860-Q1 doesn't support incremental addressing." after Table 19	52
• Changed "short" to "open" in DRV_HEADER[2:0] row, EEPROM Register 4	71

The datasheet number will be changing.

Device Family	Change From:	Change To:
LP8860-Q1	SNVSA21E	SNVSA21F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LP8860-Q1>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

LP8860AQVFPRQ1	LP8860BQVFPRQ1	LP8860CQVFPRQ1	LP8860DQVFPRQ1
LP8860HQVFPRQ1	LP8860JQVFPRQ1	LP8860LQVFPRQ1	LP8860RQVFPRQ1

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com