Customer Information Notification | 201507026l

Issue Date: 11-Sep-2015
Effective Date: 10-Oct-2015

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online

QUALITY

Management Summary
Marking error on line C of product ASC8850AET and ASC8852AET

Change Category

[ ] Wafer Fab process	[ ] Assembly Process	[X] Product Marking	[ ] Design
[ ] Wafer Fab materials	[ ] Assembly Materials	[ ] Electrical spec./Test coverage	[ ] Mechanical Specification
[ ] Wafer Fab location	[ ] Assembly Location	[ ] Test Location	[ ] Packing/Shipping/Labeling

Marking error ASC8850AET & ASC8852AET

Information Notification

Marking error found on line C of product ASC8850AET and ASC8852AET. Wrong fab letter indication was used. 'sb'is the correct fab location. These products were marked as 'sa' no changes on fab location, just errors found in the system. See also attached updated PQIP.

Why do we issue this Information Notification
Error made in product marking on line C, wrong location letter used, products should be marked with 'sb'

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.
Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP's Quallity Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

View Notification	Subscription	Support