



Document Number: D06091-A-A2127

Date: Apr.,01,2023

## **New Design In Stop Notice**

**【Common Mode Choke Coil】 DLP1ND, DLP2AD, DLP31, DXP2AB, NFP0RSA series**

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.

This is the official notification that some of our products detailed below shall be out of sales promotion with the immediate effect.

Please review this, and refrain from designing the products affected into your new models and projects. Your understanding and support are highly appreciated.

### **1. Product Type, Customer/Murata/Alternative Part Numbers:**

Product Type: **【Common Mode Choke Coil】**

DLP1ND series  
DLP2AD series  
DLP31 series  
DXP2AB serie  
NFP0RSA series

Please refer to the attached documents for detailed Part Numbers' information.

### **2. Reasons/Background:**

Decrease in orders and deterioration of production efficiency.

Also, please be informed that these parts will be withdrawn.

The official notification of the Product Withdrawal will be submitted about three years later.

### **3. Contact Window:**

Should you have any questions or concerns, please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Product Engineering Sec.5 Marketing & Promotion Dept. EMI Filter Division

Senior Manager : Yohei TSUDA

Murata  
Part Number

---

DLP2ADA350HL4L  
DLP2ADA900HL4L  
DLP2ADN121HL4L  
DLP2ADN161HL4L  
DLP2ADN201HL4L  
DLP2ADN241HL4L  
DLP2ADN281HL4L  
DLP2ADN670HL4L  
DLP2ADN900HL4L  
DLP31DN131ML4L  
DLP31DN201ML4L  
DLP31DN321ML4L  
DLP31DN441ML4L  
DLP31DN900ML4L  
DLP31SN121ML2L  
DLP31SN221ML2L  
DLP31SN551ML2L  
DXP2ABN7514TL