



## Not Recommended for New Design: DS2 Series Relays

NRFND.PG0001.10.9.2020

10.9.2020

<b>About This Notice:</b>	The DS2 Series Relays are Not Recommended For New Design due to future plans for discontinuation.
<b>Features:</b>	
<b>Effective Date:</b>	Immediate
<b>Affected Parts and/or Replacements:</b>	See Attached. Includes all custom products. There are no direct replacements.
<b>Datasheet(s):</b>	See Attached.
<b>Notes:</b>	DS1 Series Relays are not included in this Notice and remain active.

## **Panasonic NRFND.PG0001.10.9.2020 DS2 Series Relays**

### **Part Number**

DS2E-S-DC3V  
DS2E-S-DC5V  
DS2E-S-DC6V  
DS2E-S-DC9V  
DS2E-S-DC12V  
DS2E-S-DC24V  
DS2E-S-DC48V  
DS2E-SL2-DC3V  
DS2E-SL2-DC5V  
DS2E-SL2-DC6V  
DS2E-SL2-DC9V  
DS2E-SL2-DC12V  
DS2E-SL2-DC24V  
DS2E-SL2-DC48V  
DS2Y-S-DC1.5V  
DS2Y-S-DC3V  
DS2Y-S-DC5V  
DS2Y-S-DC6V  
DS2Y-S-DC9V  
DS2Y-S-DC12V  
DS2Y-S-DC24V  
DS2Y-S-DC24V-H350  
DS2Y-S-DC48V