

Product Withdrawal Notice

LFB21*BA1/4/A, LFB21*BB1, LFB21*BC, LFB2H*SY, LFB31*SW, LFB32*SA, LFE32*EB,
LFH2H*RA1, LFL18*TC3/E, LFL18*TD1/2, LFL21*TC1/A/K
LDB18*C/G/K/M, LDB21*C, LDB31, LDB32
LDC18*B/F/G, LDC21*B/D/E/H/N/J/K, LDC31, LDC32, LDC43, LDD18*A/B, LDD21*A
LFD18*DP3/4/B/C, LFD21*DC1/2/3/4, LFD21*DP1/2/3/4/5/6, LFD32*DC,
LDF18*E, LDF32*M, LFP15*004/033/038/045/089 Series

Dear. Valued Customer

Thank you very much for your great and continued support for business with Murata.
This is the official notification that some of our products will be discontinued as detailed below.
Please review this, and place Last Time Buy Order by the Last Time Order Due Date as needed.
Your understanding and support are highly appreciated.

1. Product Type, Customer/Murata/Alternative Part Numbers:

LFB21*BA1/4/A, LFB21*BB1, LFB21*BC, LFB2H*SY, LFB31*SW, LFB32*SA,
LFE32*EB, LFH2H*RA1, LFL18*TC3/E, LFL18*TD1/2, LFL21*TC1/A/K
LDB18*C/G/K/M, LDB21*C, LDB31, LDB32
Product Type: LDC18*B/F/G, LDC21*B/D/E/H/N/J/K, LDC31, LDC32, LDC43, LDD18*A/B,
LDD21*A
LFD18*DP3/4/B/C, LFD21*DC1/2/3/4, LFD21*DP1/2/3/4/5/6, LFD32*DC,
LDF18*E, LDF32*M, LFP15*004/033/038/045/089 Series

Please refer to the attached documents for detailed Part Numbers' information.

2. Reasons/Background:

End-of-Life (EOL) of the products mentioned above has been decided
due to the discontinuance of materials used in the products.

3. Product Withdrawal Schedule:

Last Time Order Due (*): 03. 31, 2022
Last Shipment Date: 09. 30, 2022

* : Last Time Order is the subject to Minimum Order Quantity and Package Quantity.
Order Cancel and Product Return can be accepted only in the case of quality issue.
Please place Last Time Buy Order by the Last Time Order Due Date as needed.
We cannot receive any orders after Last Time Order Due.

4. Contact Window:

Should you have any questions or concerns,
please contact Murata Sales, Representative, or Distributor in your area.

Truly Yours. Thank you.

Murata Manufacturing, Co., Ltd.

Planning Sec. RF Discrete Products Dept.

Module Business Unit RF Device Dev./Senior Mnager

Jiro Shibata

Murata
Part Number

Alternative
Part Number

LDB212G4020C-001	LDB181G7FAAEA046
LDB212G4005C-001	N/A
LFB212G45BA1A220	N/A
LDB182G4505C-110	N/A
LDB182G4510C-110	LDB181G7BAAEA045
LDB182G4520C-110	LDB181G7FAAEA046
LDB211G9010C-001	LDB181G7BAAEA045
LDB211G9020C-001	LDB181G7FAAEA046
LDB212G4020C-001	LDB181G7FAAEA046
LFB212G45BA1A220	N/A
LFL211G44TC1A014	N/A
LFL21902MTC1A018	LFL18915MTC5C311
LFL21915MTC1A027	LFL18924MTC1A052