



Product Change Notification

Current Date: 25-Apr-2016

TE Connectivity

Product Change Notification: P-16-012959

PCN Date: 21-APR-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Removing 10-32 screws from patch panel kits

Description of Changes
Removing 10-32 screw hardware kits from standard patch panel kits. Patch panel kits will still be supplied with 12-24 rack mounting hardware kits.

Reason for Changes:
Customer Request. Voice of the customer was for the majority of applications, 10-32 screws were not being used for patch panel mounting to equipment racks. Most North America rack manufactures use 12-24 tapped holes for panel mounting. Other regions no longer supply rack mounting hardware with panel kits.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	22-APR-2016
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	30-SEP-2016

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1479154-2	NO			"E98515-000", "AMP-0-1479154-2"			
1933307-1	NO			"EE3151-000"			
406330-1	NO			"AMP-0-0406330-1", "E45802-000"			
406331-1	NO			"296086-000", "AMP-0-0406331-1"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1479154-2	NO			"E98515-000", "AMP-0-1479154-2"			
1933307-1	NO			"EE3151-000"			
406330-1	NO			"AMP-0-0406330-1", "E45802-000"			
406331-1	NO			"296086-000", "AMP-0-0406331-1"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1479154-2	NO			"E98515-000", "AMP-0-1479154-2"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1933307-1	NO			"EE3151-000"			
406330-1	NO			"AMP-0-0406330-1", "E45802-000"			
406331-1	NO			"296086-000", "AMP-0- p406331-1"			