



Product Discontinuance

Document #:PD25141XB

Issue Date:15 Dec 2022

Title of Change:	4Q2022 Product Discontinuance Notice - Batch 5 (Standard)
Last Time Buy Date:	15 Jun 2023
Last Ship Date:	15 Dec 2023
Contact information:	Contact your local onsemi Sales Office or PCN.Support@onsemi.com
Type of notification:	Customers must notify onsemi (< PCN.Support@onsemi.com >) in writing within 90 days of receipt of this notification if they consider the discontinued product to be "Sole Source." onsemi and the customer may negotiate an appropriate End-of-Life.

Description and Purpose:

In an attempt to minimize the number and frequency of product discontinuance notices to its customers, onsemi is publishing this quarterly product discontinuance notification.

Some of the devices contained in this notice may be part of a product portfolio renewal process or a manufacturing facility closure. onsemi continually monitors worldwide sales and billings activities on all the products offered to its customers.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

onsemi wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

onsemi has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, onsemi has partnered with Rochester Electronics and Flip Electronics who will carry any remaining device inventory to potentially allow for a continued source after onsemi has completed its business process

PLEASE NOTE: onsemi may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

Japan

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, onsemi ALLOWS SIX (6) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER TWELVE (12) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

Device to be Discontinued	Replacement part	Supplier
NL27WZ08MU1TWG	#NONE	#NA
NLX1G99DMUTWG	#NONE	#NA
FAN4174IS5X	LM7301SN1T1G	onsemi
FSA1156L6X	FSA5157L6X	onsemi
PPF1006	NCP330MUTBG	onsemi
FAN4274IMU8X	NCV952DTBR2G	onsemi
NUD3124DMT1G	#NONE	#NA
FGH40N60SMDF	#NONE	#NA
NUD3112DMT1G	#NONE	#NA
FDMF6707B	#NONE	#NA
FDMF6707C	#NONE	#NA
FDMF6821A	#NONE	#NA
FDMF6821B	#NONE	#NA
FDMF6823A	#NONE	#NA
FDMF6823B	#NONE	#NA
FDMF6824B	#NONE	#NA
PPF2700MPX	#NONE	#NA
PPF2702MX	#NONE	#NA
NCP303150MNTWG	#NONE	#NA
NCP303151AMNTWG	#NONE	#NA
NCP303151MNTWG	#NONE	#NA
NC7SB3157L6X	FSA5157L6X	onsemi
PPF2123	#NONE	#NA
LE25U20AFD-AH	LE25U20AMB-AH	onsemi
LE25U40CMDTWG	LE25U40CMC-AH	onsemi
FDS8978	#NONE	#NA
NTHS5441T1G	#NONE	#NA
NTGS3433T1G	#NONE	#NA
NTMFD4C20NT1G	#NONE	#NA
MURD340T4G	MURD550PFT4G	onsemi
MURD530T4G	MURD550PFT4G	onsemi
NTNS3190NZT5G	#NONE	#NA
NTMFS5H414NLT1G	#NONE	#NA

MC74VHC1G86DFT1G	#NONE	#NA
NC7WP00L8X	#NONE	#NA
NC7WV07L6X	#NONE	#NA
NC7SV08L6X	#NONE	#NA
NC7SP126L6X	#NONE	#NA
NL17SG373DFT2G	NL17SG373ADFT2G	onsemi
NL17SG86DFT2G	#NONE	#NA
NC7SP57P6X	#NONE	#NA
74AUP1G97L6X	#NONE	#NA
74AUP1G57L6X	#NONE	#NA
NC7SV11L6X	#NONE	#NA
NC7SP08P5X	#NONE	#NA
NC7SP126P5X	#NONE	#NA
NL17SG86P5T5G	#NONE	#NA
NC7SP38L6X	#NONE	#NA
NOI4SM6600A-QDC	NOIX1SN8000B-LTI	onsemi
NCP3230MNTXG	NCP3284MNTXG	onsemi
NCP431ACLPRAG	TL431ACLPRAG	onsemi
TL431BCLPG	TL431BCLPRAG	onsemi
FJH1100	#NONE	#NA
FJH1101	#NONE	#NA
2N6338G	#NONE	#NA
NUD3160DMT1G	#NONE	#NA
MDC3105LT1G	#NONE	#NA
NUD3124LT1G	#NONE	#NA
NC7WB66K8X	#NONE	#NA
FSUSB30UMX	FSUSB42UMX	onsemi
FSA4159P6X	FSA5157L6X	onsemi
RURD420S9A	MURD620CTT4G	onsemi
NTHS5404T1G	#NONE	#NA
MBRD660CTRLG	MBRD660CTT4G	onsemi
NC7SVL08P5X	#NONE	#NA
NC7SV126P5X	#NONE	#NA
NC7SVU04P5X	#NONE	#NA
NC7SVL32P5X	#NONE	#NA
MJD42C1G	MJD42CT4G	onsemi
NUD3160LT1G	#NONE	#NA



Product Discontinuance

Document #:PD25141XB

Issue Date:15 Dec 2022

FPF2700MX	#NONE	#NA
FSA4157AP6X	FSA5157L6X	onsemi
NC7SB3157P6X	FSA5157L6X	onsemi

Appendix A: Changed Products

DIKG: DIGI-KEY (page 1 of 2)

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
NC7SB3157P6X			FSA5157L6X	onsemi
FPF2700MX			#NONE	#NA
NUD3160LT1G			#NONE	#NA
MJD42C1G			MJD42CT4G	onsemi
NC7SVL32P5X			#NONE	#NA
NC7SVU04P5X			#NONE	#NA
NC7SV126P5X			#NONE	#NA
NC7SVL08P5X			#NONE	#NA
MBRD660CTRLG			MBRD660CTT4G	onsemi
NTHS5404T1G			#NONE	#NA
FSA4159P6X			FSA5157L6X	onsemi
FSUSB30UMX			FSUSB42UMX	onsemi
NC7WB66K8X			#NONE	#NA
NUD3124LT1G			#NONE	#NA
MDC3105LT1G			#NONE	#NA
NUD3160DMT1G			#NONE	#NA
2N6338G			#NONE	#NA
FSA4157AP6X			FSA5157L6X	onsemi
FJH1100			#NONE	#NA
FJH1101			#NONE	#NA
NCP431ACLPRAG			TL431ACLPRAG	onsemi
TL431BCLPG			TL431BCLPRAG	onsemi
NCP3230MNTXG			NCP3284MNTXG	onsemi
NC7SP38L6X			#NONE	#NA
NOII4SM6600A-QDC			NOIX1SN8000B-LTI	onsemi
NC7SP08P5X			#NONE	#NA
NC7SP126P5X			#NONE	#NA
NC7SV11L6X			#NONE	#NA
74AUP1G97L6X			#NONE	#NA
74AUP1G57L6X			#NONE	#NA
NL17SG86DFT2G			#NONE	#NA
NC7SP57P6X			#NONE	#NA
NC7SP126L6X			#NONE	#NA
NL17SG373DFT2G			NL17SG373ADFT2G	onsemi
NC7WV07L6X			#NONE	#NA
NC7SV08L6X			#NONE	#NA
NTMFS5H414NLT1G			#NONE	#NA
MC74VHC1G86DFT1G			#NONE	#NA
NTNS3190NLT5G			#NONE	#NA
MURD530T4G			MURD550PFT4G	onsemi
NTMFD4C20NT1G			#NONE	#NA
MURD340T4G			MURD550PFT4G	onsemi
NTHS5441T1G			#NONE	#NA
NTGS3433T1G			#NONE	#NA
LE25U40CMDTWG			LE25U40CMC-AH	onsemi
FDS8978			#NONE	#NA
FPF2123			#NONE	#NA
LE25U20AFD-AH			LE25U20AMB-AH	onsemi
NCP303151MNTWG			#NONE	#NA
NC7SB3157L6X			FSA5157L6X	onsemi
NCP303150MNTWG			#NONE	#NA
FPF2700MPX			#NONE	#NA
FPF2702MX			#NONE	#NA
FDMF6823B			#NONE	#NA
FDMF6821A			#NONE	#NA
FDMF6823A			#NONE	#NA
NUD3112DMT1G			#NONE	#NA
FDMF6707C			#NONE	#NA
NUD3124DMT1G			#NONE	#NA
FGH40N60SMDF			#NONE	#NA

Appendix A: Changed Products

PCN#: PD25141XB
Issue Date: Dec 15, 2022

DIKG: DIGI-KEY (page 2 of 2)

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
FAN4274IMU8X			NCV952DTBR2G	onsemi
FPF1006			NCP330MUTBG	onsemi
FAN4174IS5X			LM7301SN1T1G	onsemi
FSA1156L6X			FSA5157L6X	onsemi
NLX1G99DMUTWG			#NONE	#NA