



# Product Change Notice

PCN Number: 13-0623-03A  
Issue Date: 05-DECEMBER-2013

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

<b>PRODUCTS AFFECTED:</b>	CDK3401CTQ48	SP503CM-L	SP510EM-L	SP510EM-L/TR	SP508ECF-L
	SP508EEF-L	SP510CM-L/TR	SP510CM-L	SP510ECF-L	SP510EEF-L
	XRT7300IVTR-F	XRT81L27IV-F	ST16C554CQ64-F	ST16C554CQ64TR-F	ST16C554DCQ64-F
	ST16C554DCQ64TR-F	ST16C554DIQ64-F	ST16C554DIQ64TR-F	ST16C654CQ64-F	ST16C654CQ64TR-F
	ST16C654DCQ64-F	ST16C654DCQ64TR-F	ST16C654DIQ64-F	ST16C654DIQ64TR-F	ST16C654IQ64-F
	ST16C654IQ64TR-F	XRT5793IV	XRT5795IV	XRT5897IV	XRT59N97IV-F
	XRT7300IV-F				

## CHANGE CATEGORY:

- |  |                                    |   |
|--|------------------------------------|---|
| <input type="checkbox"/> Material                                  | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                                    | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Assembly Site |                                    |   |

## DESCRIPTION OF CHANGE:

Addition of an alternate qualified assembly site, ASE Chung-Li (Taiwan)

## IMPACT OF CHANGE:

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 05-March-2014

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

### PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.